


QUICK START GUIDE





CR2032

Elevation Adjustment

Increase brightness

Tap to power on

Decrease brightness

Hold for 3 Seconds to power off

Windage Adjustment